

# VERIFYING W600 & W601 USING MASTER GAGE W785A

MUST READ "2" ON FINGER  
AT "0" ON GAGE BODY  
WITH HEEL OF FINGER  
RESTING ON GAGE

VERIFY LOCATION  
WITNESS GROOVE NOTCH

MUST SEAT

"0" AT "0"  
ALRIGHT TO BE SLIGHTLY ABOVE  
REFLECTS UNUSED WEAR ALLOWANCE  
REJECT IF "0" LINE OFF BODY

MUST SEAT

MUST NOT SEAT

MUST SEAT

NOTCH ALIGNS  
WITH "12" LINE

MUST NOT SEAT

